



AUTO INSPECTIONS DIRECT

CLASSIC/EXOTIC CAR INSPECTION REPORT

INSPECTION NUMBER	DATE	TIME IN	TIME OUT
2444	10/5/2018	10AM	1230PM

SELLER	John Salas	VEHICLE LOCATION	Beverly Hills Car Club
ADDRESS	4576 1/2 Worth St.	ADDRESS	4576 1/2 Worth St.
CITY/STATE/ZIP	Los Angeles, CA 90063	CITY/STATE/ZIP	Los Angeles, CA 90063
TELE#	(310) 975-0272	TELE#	(310) 975-0272

MODEL YEAR	1979	ODOMETER READING	32042(a)
MAKE	Ferrari	VIN #	[REDACTED]
MODEL	308 GTB	ENGINE DISPLACEMENT	2.9L
BODY STYLE	coupe	ENGINE #	01286
EXTERIOR COLOR	black	# OF CYLINDERS	V8
INTERIOR COLOR	tan	DRIVE TRAIN	rear wheel drive
INTERIOR FABRIC	leather	DOCUMENTATION	California title

NOTES Stock#: 9507

Minoru Maeda

tele#: [REDACTED]

e*mail: [REDACTED]

a. odometer does not operate/cannot verify actual mileage

EXTERIOR CONDITION

		satisfactory	repair		NOTES/DAMAGE	GRADE
1	front bumper	X				
2	grille	X			all slats present/trim in good condition	4
3	head lights	X			operate as designed/hydraulics OK	4
4	running lights		X		do not operate/housing & lenses in good condition	2.5
5	front turn signals		X		do not operate/housing & lenses in good condition/column mast OK	2.5
6	rear turn signals		X		do not operate/housing & lenses in good condition	2.5
7	brake lights	X			operate as designed/housing & lenses in good condition	4
8	reverse lights		X		do not operate/housing & lenses in good condition	2.5
9	license plate lights		X		DS bulb out	3
10	hazard lights	X			operate as designed	4
11	windshield wipers	X			blades, arms & motor in good working order	4
12	windshield washers		X		no fluid in reservoir	3
13	hood/bonnet	X		NF	opens & closes easily/cabin release operates as designed/aligns flush with adjacent panels/underside clean	4
14	D/S fender	X		NF	aligns flush with adjacent panels	4
15	D/S front door	X		NF	opens easily/closes securely/hangs straight/aligns flush with adjacent panels/latch in good condition/no rust on underside	4
16	D/S side mirror		X		missing	2
17	D/S quarter panel	X		NF	aligns flush with adjacent panels	4
18	trunk/rear deck	X		NF	opens & closes easily/cabin release operates as designed/louvers & trim in good condition/aligns flush with adjacent panels	4
19	rear bumper	X				4
20	P/S fender	X		NF	aligns flush with adjacent panels	4
21	P/S front door	X		NF	opens easily/closes securely/hangs straight/aligns flush with adjacent panels/latch in good condition/no rust on underside	4
22	P/S side mirror		X		missing	2
23	P/S quarter panel	X		NF	aligns flush with adjacent panels	4
24	roof	X		NF	trim in good condition	4
25	external glass	X			cannot verify DSF window-all other glass OK	3.5
26	paint condition	X			holding up well	3.5
NF=NO FILLER DS=DRIVER SIDE PS=PASSENGER SIDE					EXTERIOR AVERAGE:	3.5

NOTES

The exterior looks good save for the missing side view mirrors. Some external electrical needs attention.

INTERIOR CONDITION

		satisfactory	repair		NOTES/DAMAGE	GRADE
1	dashboard	X			upholstery, façade & under dash in good condition	4
2	dashboard lights		X		do not operate	2.5
3	interior lights	X			rear dome light works as designed	4
4	gauges		X		none of the gauges (including tach & odometer) are working	2
5	glove box				not equipped	
6	console	X			shifter, shifter knob & shifter plate in good condition/all switches and knobs function as designed	3.5
7	rear view mirror	X			base, housing & glass in good condition/adjusts securely	4
8	visors	X			upholstery in good condition/adjust securely/stay in place	4
9	headliner	X			clean/no rips or tears	4
10	steering wheel	X			rim, spokes & hub in good condition	4
11	horn	X			operates as designed	4
12	air conditioning		X		does not blow cold/vents, knobs & switches are all OK	3
13	heater/defroster	X			operates as designed	3.5
14	defroster/rear				cannot verify	
15	radio/aerial	X			radio in good condition/power aerial does not operate	3.5
16	audio gear				cannot verify operation of CD player	
17	front door panels	X			upholstery & trim in good condition	4
18	power windows		X		DS door switches not working/DS window is down	2.5
19	door locks	X			operate as designed with key provided	3.5
20	front seats	X			upholstery in good condition/slide adjust & forward fold as designed	4
21	front flooring	X			carpeting & mats in decent condition	3.5
22	rear seats				not equipped	
23	rear flooring	X			carpeting in good condition	4
24	floor pans				cannot expose	
25	molding/trim	X			DS door molding loose	3.5
26	trunk interior	X			clean/no rust	3.5
27	trunk trim	X				3.5
NF=NO FILLER DS=DRIVER SIDE PS=PASSENGER SIDE						3.5
						INTERIOR AVERAGE: 3.5

NOTES

The major interior issue is that none of the dash gauges are operating. The A/C system may require a re-charge.

ENGINE BAY/UNDERCARRIAGE

		satisfactory	repair	not equipped	NOTES/DAMAGE	GRADE
1	engine bay	X			no rust/fire wall in good condition	4
2	battery	X			holds charge/no rust or corrosion in tray	4
3	radiator	X			no rust or leaks/pressure cap secure	4
4	belts	X				3.5
5	hoses	X				3.5
6	clamps	X				3.5
7	wiring	X				3.5
8	engine oil	X				3.5
9	transmission fluid			X		3.5
10	brake fluid	X				3.5
11	coolant	X				3.5
12	ENGINE BAY LEAKS	X			no sign of any current or prior fluid leaks	4
13	exhaust system	X			muffler, pipes, hangers, cat converter & tips in good condition	3.5
14	rack & pinion	X			no rust or leaks	3.5
15	F. bushings/boots	X			all in good condition	3.5
16	front brakes	X		DISK	rotors, disks, calipers & hoses in good condition/no rust or leaks	4
17	front suspension	X			surface rust on shocks/springs in fair condition	3
18	rear brakes	X		DISK	rotors, disks, calipers & hoses in good condition/no rust or leaks	4
19	rear axles		X		PS boot loose/no rust/secure connections	3
20	rear suspension	X			surface rust on shocks/springs in fair condition	3
21	differential	X			clean/no rust/secure connections/no leaks	4
22	UNDERSIDE LEAKS	X			none seen	4
23	rust	X			none seen	4
24	frame	X			appears undamaged with no evidence of prior repairs	4
					ENGINE BAY/UNDERCARRIAGE AVERAGES:	3.7

NOTES

Appears to be a reasonably well-maintained vehicle with no rust or leaks anywhere. There is a patch screwed into the apron near the center front.

TIRES & WHEELS

		SIZE	SPEED INDEX	TREAD DEPTH	Manufacturer	GRADE
1	D/S front tire	225/50/R16	n/a	10	Cooper	4.5
2	P/S front tire	225/50/R16	n/a	10	Cooper	4.5
3	D/S rear tire	225/50/R16	n/a	9	Cooper	4.5
4	P/S rear tire	225/50/R16	n/a	9	Cooper	4.5
5	spare	205/70/R14	XWX	8	Michelin	4
		satisfactory	repair	not equipped	Comments	
6	D/S front wheel	X				4
7	P/S front wheel	X				4
8	D/S rear wheel	X				4
9	P/S rear wheel	X				4
10	spare wheel	X				4
11	jack/wrench	X				4
12	knock off hammer			X		4
13	tool kit	X				4
14	manuals	X				4
					plenty of maintenance records as well	4
					TIRES & WHEELS AVERAGE:	4.2

NOTES

The four mounted Cooper tires have plenty of tread life remaining and are in good condition. There are no signs of any uneven tread wear or side wall cracking. The spare is mis-matched but in usable condition.

TEST DRIVE

		satisfactory	repair	not equipped	NOTES/DAMAGE	GRADE
1	engine starting	X			catches & turns on the first try	4
2	engine idle		X		misfires when engine is turned off-needs tune up	2.5
3	acceleration	X			plenty of power from the 2.9L/V8	4
4	compression	X			not tested/feels strong with no misfires, rattles or odd noises noted	3.5
5	steering	X			no play in the steering wheel	4
6	handling	X			holds the road well on all surfaces and speeds	4
7	suspension	X			firm providing a safe, stable & comfortable ride	4
8	braking	X			solid with no pulls felt or noises heard when applied	4
9	hand brake	X			holds vehicle in place as designed	4
10	alignment		X		pulls heavy to the left	2.5
11	transmission	X			5 speed engages all gears easily & smoothly with no odd noises	4
12	clutch	X			plenty of adhesion & very tight/no slips or noises	4
13	4X4/AWD			X		
					TEST DRIVE AVERAGE:	3.7

NOTES

The engine is in need of a tune up and the vehicle needs a front-end alignment. The test drive was performed on city streets of varying surface conditions as well as the freeway with a maximum speed of 70mph.

VEHICLE SUMMARY

page 7

A very nice looking vehicle with several age-appropriate flaws as noted. The actual mileage is suspect since the odometer does not operate. Some of the exterior lighting needs repair. The paint is in good condition. The vehicle does not appear to have sustained any prior collision damage. The cabin is in good condition as are the seats and carpeting. However, none of the gauges are operating and the A/C, heater & defroster made require some service as well. The power aerial is not working and the mast is broken. The engine bay is clean with no leaks or rust. The undercarriage is also clean with no rust or leaks. As mentioned, the vehicle appears to have been well maintained. It drives very well but does need a tune up and front end alignment. There are no signs of abusive driving or excess wear and tear.



Matt Lange
AUTO INSPECTIONS DIRECT

GRADE 5/EXTRA CLEAN

Vehicle is in excellent condition (almost concourse) with only minor defects in panel surfaces as noted in the report for this vehicle. The body panels require no conventional body or paint work but may have limited, high-quality repairs performed. There are no missing, broken or damaged parts that require repair or replacement. The interior compartment has no cuts, tears or burns that require repair and does not show signs of wear. The vehicle's frame/structure has not been repaired or altered and is expected to measure to published specifications. Vehicle is mechanically sound and all accessories are operating as designed. All fluid levels are full and clean. All tires are near new or better.

GRADE 4/CLEAN

A better than average vehicle with minor chips or scratches in panel surfaces as noted in the report for this vehicle. This vehicle may require minor conventional body and/or paint work or removal of small dents/dings that have not broken the paint using *PAINTLESS DENT REPAIR*. The body of the vehicle may have had high quality conventional repairs. A minor missing or broken part may require repair or replacement as noted in this report. The interior is clean and may show minimal wear. The vehicle may have sustained cosmetic or light collision damage and been repaired to collision industry standards. The frame/structure has not been damaged or repaired and is expected to measure up to published specifications. Vehicle is mechanically sound and all accessories are operable as designed. Vehicle may need fluid serviced or tires rotated. Only scheduled maintenance will be necessary. Tires will be good or better.

GRADE 3/AVERAGE

The average vehicle will have normal wear and tear (for example: parking lot dings, small scratches, chips and/or minor broken parts). It may require some conventional body repair and/or paint work or replacement parts as noted in the report for this vehicle. The interior will show signs of normal wear and usage requiring repair or replacement parts as noted. Prior repairs may have been performed on this vehicle at an acceptable quality level. The vehicle may have sustained cosmetic or light collision damage and repaired to collision industry standards. The frame/structure has not been damaged or repaired and is expected to measure up to published industry standards. Vehicle is mechanically sound but may require maintenance or minor accessory repair. The fluid levels may be low or require replacement. Tires will be average or better.

GRADE 2/BELOW AVERAGE

Vehicle shows signs of abnormal wear and tear. The body has dents, scratches and body panels that may require replacement as noted in the report for this vehicle. Broken or missing parts are to be expected. The interior shows signs of excessive wear with burns, cuts or tears and non-removable stains as noted. This vehicle may have multiple prior repairs performed at sub-standard levels that may include repaired or unrepaired collision and/or frame/structure damage. The frame/structure is not expected to measure up to published specifications. Vehicle may have mechanical damage that prohibits vehicle from operating properly or safely. Repairs can be made but engine and/or transmission may be in poor condition. Operation of accessories is questionable. Fluids are low and require replacement. Worn tires are to be expected.

GRADE 1/ROUGH

This vehicle has been severely abused or has sustained major collision damage. It is cost prohibitive to extensively recondition or repair this vehicle by automotive industry standards. The frame/structure is not expected to measure up to published specifications. Although operable, this vehicle may be near the end of its useful life. Operation of accessories is doubtful.

GRADE 0/EXTRA ROUGH

This vehicle is inoperative. Unit is good for parts only. Mechanical and body parts may be inoperable, disconnected, damaged or missing.

STATE OF CALIFORNIA

CERTIFICATE OF TITLE

19418040442

AUTOMOBILE

VEHICLE ID NUMBER

2D

BODY TYPE MODEL

2D

UNLADEN WEIGHT

AX

YR 1ST SOLD

LR 2018

FUEL

G 03/18/18

CLASS

LR 2018

TRANSFER DATE

03/18/18

YR

ZR 9507

YR MODEL

1979 FERRA

PLATE NUMBER

4FTM724

REGISTRATION

EXPIRATION DATE

07/24/2006

ISSUE DATE

04/04/18

FEES PAID

\$15

EQUIP/MT/TRUST NUMBER

9507

ODOMETER DATE

9507

ODOMETER READING

04/04/18

REGISTERED OWNER(S)

BEVERLY HILLS CAR CLUB

44514

4576 1/2 WORTH ST

LOS ANGELES CA 90063

VEHICLE HISTORY



VOID WITHOUT BEAR WATERMARK. HOLD TO LIGHT TO VIEW.

VOID WITHOUT BEAR WATERMARK. HOLD TO LIGHT TO VIEW.

I certify (or declare) under penalty of perjury under the laws of the State of California that THE SIGNATURE(S) BELOW RELEASES INTEREST IN THE VEHICLE. X

1a DATE X SIGNATURE OF REGISTERED OWNER

1b DATE X SIGNATURE OF REGISTERED OWNER

Federal and State law requires that you state the mileage upon transfer of ownership. Failure to complete or providing a false statement may result in fines and/or imprisonment.

The odometer now reads (no tenths), miles and to the best of my knowledge reflects the actual mileage unless one of the following statements is checked. Mileage is VOID if altered or erased.

WARNING Odometer reading is not the actual mileage. Mileage exceeds the odometer mechanical limits.

I certify (or declare) under penalty of perjury under the laws of the State of California that the foregoing is true and correct.

DATE X TRANSFEROR/SELLER SIGNATURE(S) DATE TRANSFER/BUYER SIGNATURE(S)

PRINTED NAME OF SELLER/OF AGENT SIGNED FOR A COMPANY PRINTED NAME OF BUYER/OF AGENT SIGNED FOR A COMPANY

Any change of Lienholder (holder of security interest) must be reported to the Department of Motor Vehicles within 10 days.

LIENHOLDER(S)

- 2. X Signature releases interest in vehicle. (Company names must be countersigned) Release Date

CA180360553 001657 REG. 17.30FS (REV.02/2016)

KEEP IN A SAFE PLACE - VOID IF ALTERED